

1/5
worledge (wyc)
YOR 920030410 U31





FIG. 1

FIG. 2

Phase Diagram for Two Identical Coupled Layers

H_i, H



To get units of Oe, read
 $4\pi M_s n_{x,y} t/b$ for $n_{x,y}$ and
 $J/M_s t$ for j .

FIG. 3




FIG. 4




FIG. 5

